Downloaded on 30 September 2024 08:11 | Tri Okta Ervina - ENG BJS

TABLE A6-8
Inner Piping for Rear Casing

NOTE
- Remark ※ : Parts to be replaced at each regular inspection.
- Not Remark ※ : Replace with a new one depending on the condition.
- "Order Q'ty" shows parts quantity for two fans.
- (Quantity required normal maintenance.)

EQUIPMENT No.	MARKS	DESCRIPTION	PART NO	1-PIECE WEIGHT (kg)	REMARK	ORDER Q'TY	DELIVERY TIME (Month)	REPLACEMENT SCHEDULE (Year)
(H) INNER PIPIG FOR REAR CASING	a	FLEXIBLE HOSE (FOR SUPPLY OIL)	FIG-8-ⓐ	—	※	2	5	every 2years
	b	FLEXIBLE HOSE (FOR RETURN OIL)	FIG-8-ⓑ	—	※	2	5	
	c	FLEXIBLE HOSE (FOR PILOT LEAK)	FIG-8-ⓒ	—	※	2	5	
	d	FLEXIBLE HOSE (FOR OIL SEAL LEAK)	FIG-8-ⓓ	—	※	2	5	

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HITACHI POWER SYSTEMS, LTD.(MHPS) AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MHPS OR WITH A PRIOR WRITTEN CONSENT OF MHPS NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR IN FRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

CONFIDENTIAL

Uncontrolled when printed or downloaded. Verify that this is the correct version before use.
Reproduction of part or all the contents of the document is prohibited without written permission from PT. Bhumi Jepara Service