





NO.	SPARE PARTS LIST FOR		USE		SETS PER PLANT	
	GENERATOR		CTEIL/DARAJAT GEOTHERMAL POWER PLANT UNIT III			
ITEM NO.	NAME OF PART	OUTLINE	DWG. NO. OR TYPE NO.	QUANTITY		REMARKS
				WORKING (PERSET)	SPARE	
13	R-C BLOCK		M571- 268522C C2	3	1	FOR ROTATING RECTIFIER
14	R-C BLOCK		M571- 268521C C2	3	1	FOR ROTATING RECTIFIER
15	BRUSH HOLDER	 (HOLDER ONLY)	M530- 488388	2	2	FOR EARTH BRUSH HOLDER
	SPARE BOX		M095- 4F5400 C7		1	FOR ITEM NO. 3~15

This drawing is the property of Fuji Electric Systems Co., Ltd. It is to be used only for the purpose specified. It is not to be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage and retrieval system, without the prior written permission of Fuji Electric Systems Co., Ltd.

DRAWN	M. K. Y. ku	APPROVED
CHECKED	A. Nakayama	
DATE	2005-10-31	

Fuji Electric Systems Co., Ltd.

DRAWING NO. M096-5D0461<6/6>