
## 7.3 MOTOR, FRAME, COMPRESSOR AND PARTS (LS-12 SERIES)



## **ILLUSTRATIONS AND PARTS LIST**

## 7.3 MOTOR, FRAME, COMPRESSOR AND PARTS (LS-12 SERIES)

key number	description	part number	quantity
1	nut, hex 5/8"	824210-559	2
2	motor, 40HP (230/460V) Smotor, 50HP (230/460V) Smotor, 60HP (230/460V)	250016-692 250016-693 250016-694	1 1 1
3	support, motor (60HP) Ssupport, motor (40 and 50HP)	250018 - 536 250017 - 490	1 1
4	nut, hex 3/8"-16	824206-337	12
5	washer, springlock 3/8"	837506-094	14
6	adapter, motor/compressor	250014-882	1
7	washer, springlock 5/8"	837510-156	10
8	capscrew, hex 5/8"-11 x 1 1/2"	828610-150	4
9	screw, hex serrated washer 5/16" x 3/4"	829705-075	3
10	guard, coupling	250018-412	1
11	capscrew, ferry 1/2"-13 x 2 1/2" (40 and 50HP) Scapscrew, ferry 5/8"-11 x 2 3/4" (60HP)	828408-250 828410-275	6 6
12	washer, springlock 1/2" (40 and 50HP) Swasher, springlock 5/8" (60HP)	837508-125 837510-156	6 6
13	washer, conduit reducing 3" x 1 1/2"	847012-060	2
14	hub, coupling (40 and 50HP) Shub, coupling (60HP)	250018-005 250018-008	1 1
15	element, coupling (40 and 50HP) Selement, coupling (60HP)	250004-641 250018-551	1 1
16	hub, coupling (40 and 50HP) Shub, coupling (60HP)	250004-642 250018-006	1 1
17	compressor unit (I)	Consult Factory	1
18	capscrew, hex 3/8"-16 x 2 1/4	828606-225	12
19	grip, cord	250014-557	1
20	wire, type g-gc 4 ga	250014-306	4 ft.
21	support, compressor	250017-489	1
22	capscrew, hex 5/8"-11 x 1 1/4"	828610-125	6
23	frame, main	250015-817	1

(Continued on page 37)

The shaft seal is not considered part of the compressor unit in regard to the 2 year warranty, but the normal Sullair parts warranty applies. For shaft seal repairs, order shaft seal repair kit no. 02250050 – 363 (12 Series 40 and 50HP) or kit no. 02250050 – 364 (12 Series 60HP), and seal tool kit no. 602542 – 001.

PLEASE NOTE: WHEN ORDERING PARTS, ALWAYS INDICATE SERIAL NUMBER OF COMPRESSOR.

<sup>(</sup>I) There is an exchange program whereby a remanufactured compressor unit can be obtained from Sullair distributors or the factory at less cost than the owner could repair the unit. For information regarding the unit exchange program, contact your nearest Sullair representative or the Sullair Corporation.