

CHANCE[®]

MANUFACTURED BY A.B.CHANCE CO.

WARNING

These fuse links will not protect personnel from electrocution.
Hot gases and high velocity particles are expelled during interruption.
This expulsion can cause serious injury. Do not get in line with fuseholder.
Keep face and hands away from contact surfaces below fuseholder.

MADE IN USA

FUSE LINK
M30KA23

AMPS 30

TYPE K

12/04/97