

J1-Up)

Introduction


Table 1

Tools Needed	
Tool	Caterpillar Part Number
Digital Multimeter	6V-7070 Digital Multimeter or equivalent
1/4 inch Wrench	N/A
1/2 inch Wrench	N/A

This instruction describes the removal process and the installation process for the following semi-solid link solenoids:

- 37MT

Solenoid Removal Instru



WAREHOUSE STOCK CARD

Item No.

9900 : 255324 CAT E71A

Description

SOLENOID
 PN: 206-8784 CAT

Location

: C01C003

it (42MT model