

K3000™

Medium Duty - General repair and maintenance jobs in areas as mining, construction, and all types of metal fabrication



AMPERAGE RANGE

- 90 – 600 A

ELECTRODE SIZE

- Pointed - round 3.2 mm - 9.5 mm
- Jointed - round 7.9 mm - 9.5 mm
- Flat - 9.5 mm - 15.9 mm
- Half Round - 15.9 mm

AIR REQUIREMENTS

- psi – 80
- kg/cm² – 5.6
- cfm – 22
- l/min – 624

Part No.	Description
01065001	Torch Only
61065006	Torch w/2.1 m 360° Swivel Cable
61065002	Torch w/2.1 m 360° Swivel Cable & Insulated Hook-Up Kit
61065007	Torch w/3 m 360° Swivel Cable
61065003	Torch w/3 m 360° Swivel Cable & Insulated Hook-Up Kit

K4000®

Heavy Duty - Heavy metal removal applications such as weld preparations in pressure vessel shops and shipyards



AMPERAGE RANGE

- 90 – 1000 A

ELECTRODE SIZE

- Pointed - round 4.0 mm - 12.7 mm
- Jointed - round 7.9 mm - 12.7 mm
- Flat - 9.5 mm - 15.9 mm
- Half Round - 15.9 mm

AIR REQUIREMENTS

- psi – 80
- kg/cm² – 5.6
- cfm – 25
- l/min – 708

Part No.	Description
01082002	Torch Only
61082008	Torch w/2.1 m 360° Swivel Cable
61082006	Torch w/2.1 m 360° Swivel Cable & Insulated Hook-Up Kit
61082009	Torch w/3 m 360° Swivel Cable
61082007	Torch w/3 m 360° Swivel Cable & Insulated Hook-Up Kit


MANUAL GOUGING

SWIVEL CABLE ASSEMBLY OPTIONS

K3000 360° Swivel Cable



K4000 360° Swivel Cable



Part No.		Description
K3000	K4000	
70088107	70084207	2.1 m 360° Swivel Cable Assembly
70088110	70084210	3 m 360° Swivel Cable Assembly