

Tanjung Jati B Expansion (Jawa-4) Coal Fired Steam Power Plant 2 x 1,000 MW

Strategic Spare Part List

Common

Item No.	Item Name	Equipment Name	Description of Spare Parts	Supplier's Name	Configuration or Part no.	Qty per unit				Current Unit Price (USD)				Lead Time for (MO) (Months)	Sketch	Cross Reference Drawing	Expected Frequency of requirement	Remarks
						PC	CC	EW	SW	PC	CC	EW	SW					
<b>18 CONDENSATE POLISHING PLANT</b>																		
TJBSA-RECH-CPH001	0 0 LDP 1020 AP 010	OPF Regeneration Water Pump AB	Mechanical Feed Bearing, Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH002	0 0 LDR 1020 AP 010	OPF Regeneration Drain In Sump Pump AB	Mechanical Seal Bearing, Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH003	0 0 LDR 9040 AP 010	OPF Regeneration Auxiliary Drain TR Sump Pump	Mechanical Seal Bearing, Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH004	0 0 LDC 2030 AN 010	AP Blower for Regeneration Facility AB	Ric Compressor, V-Belt, Bearing and Lip Seal	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH005	0 0 LCN 8035 AP 010	Anti Unloading Pump AB	Impeller Set, Rear Cover Shaft Seal, Front Cover, Seal Set and Bearings & Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH006	0 0 LCN 3035 AP 010	Drainage Unloading Pump AB	Impeller Set, Rear Cover Shaft Seal, Front Cover, Seal Set and Bearings & Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH007	0 0 LCN 9035 AP 010	Anti Unloading Pump AB	Impeller Set, Rear Cover Shaft Seal, Front Cover, Seal Set and Bearings & Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH008	0 0 LCN 4045 AP 010	Chemical Metering Pump AB	Impeller Set, Rear Cover Shaft Seal, Front Cover, Seal Set and Bearings & Gasket	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	2 set	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH009	0 0 LD - - - - -	Pressure Gauge	Pressure Gauge	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	10 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH010	0 0 LD - - - - -	pH Sensor	pH Sensor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH011	0 0 LD - - - - -	Conductivity Sensor	Conductivity Sensor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH012	0 0 LD - - - - -	Substance Valve	Substance Valve	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	10 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH013	0 0 LDY 10 OH 100	PLC Panel	PLC Panel with LED (16 slots) (16 channels) (4 wire) (16 Channel DI Module (2 wire) (16 Channel AO Module (1 wire) (16 Channel AI Module (1 wire) Power Supply: 24VDC/2.5A/11.7W)	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	11 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH014	0 0 LCN 900 AP 010	ANTI METERING PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH015	0 0 LCN 900 AP 010	ANTI UNLOADING PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH016	0 0 LDC 2000 AN 010	AIR BLOWER FOR REGENERATION FACILITY	Blower Package	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH017	0 0 LCN 400 AP 010	CAUSTIC METERING PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH018	0 0 LCN 300 AP 010	OPF REGENERATION AMMONIUM DRAIN PIT SLUMP PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH019	0 0 LDR 1000 AP 010	OPF REGENERATION DRAIN PIT SLUMP PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH020	0 0 LDP 1000 AP 010	CAUSTIC UNLOADING PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
TJBSA-RECH-CPH021	0 0 LDP 1000 AP 010	OPF REGENERATION WATER PUMP	Pump shaft with Motor	SALCON	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	Region when demanded	-	
<b>19 OVERHAUL CRANE</b>																		
TJBSA-RECH-CHC001	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Main Inlet Disc Brake	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC002	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Auxiliary Disc Brake	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC003	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Wire Ropes for Main Hoist	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 roll	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	10 year	-	
TJBSA-RECH-CHC004	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Wire Ropes for Aux Hoist	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 roll	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	10 year	-	
TJBSA-RECH-CHC005	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Disc Brake for Crank Travel Motor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	3 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC006	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Disc Brake for Long Travel Motor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	3 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC007	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Load Sensor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC008	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Converter Set	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC009	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Resistor for Hoist Motor - Main	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC010	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Resistor for Hoist Motor - Aux	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC011	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Resistor for Crank Travel Motor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	2 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC012	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Resistor for Long Travel Motor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	2 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC013	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Limit Switch	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	2 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC014	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Non-Contact Sensor	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC015	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Switch	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC016	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Switch (Bench)	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	6 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC017	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Emergency Stop	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC018	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Cable Trolley	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	5 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	
TJBSA-RECH-CHC019	0 0 SWM 10 AE 010000	BT Overhaul Crane AB	Towing Trolley	EXCELLETT	TJBSA-LOFF-CO-004AL-ST-2010	1 pc	Later	Later	Later	Later	Later	Later	Later	TJBSA-LOFF-CO-004AL-ST-2010	TJBSA-LOFF-CO-004AL-DR-2010	4 year	-	