








Recommended Spare Parts List

TBFP BOOSTER PUMP		REF.DWG.No.	R170411902-105				
No.	PART NAME	SKETCH	MATERIAL	SUPPLY		PART No.	REMARKS
				WORKING FOR 1SET	TOTAL		
B-1	O-RING MECH. SEAL SLEEVE		FKM	2	8	115-1	Refer to P/N 12 of mechanical seal drawing "TJB56-L1-OFF-C-LAC-M-DRD-2706"
B-2	O-RING MECH. SEAL COVER		FKM	2	8	115-2	Refer to P/N 6 of mechanical seal drawing "TJB56-L1-OFF-C-LAC-M-DRD-2706"
B-3	O-RING BEARING BRACKET		NBR	2	8	115-3	A= 5.7mm d= 269.3mm (G270)
B-4	O-RING BEARING BRACKET		NBR	2	8	115-4	A= 5.7mm d= 500mm
B-5	O-RING DEFLECTOR		NBR	3	12	115-5	A= 3.53mm d= 94.84mm (AS568-240)
B-6	GASKET CASING		SUS316 GRAPHITE	1	4	117-1	D= 755mm d= 730mm t= 4.5mm
B-7	GASKET CASING		SUS316 GRAPHITE	1	4	117-2	D= 730mm d= 709mm t= 4.5mm

(Note)

Q'ty mention on this document is showing installed q'ty.
Spare Parts q'ty shall refer to TJB56-L1-OFF-C-00-G-LST-0021.



EBARA CORPORATION