

Tanjung Jati B Expansion (Jatubek) Coal Fired Steam Power Plant 2 x 1,000 MW

Form for List of Strategic Spare Parts

Item No.	(R1) Item No.	Equipment Tag Number (KKS)										Equipment Name	Description of Spare Items	Supplier's name	catalogue or part number	Qty per 2 Units Proposed by MHPS		Qty per 2 Units requested by BLP (input on Oct 14 2018 and May 2023)		Qty Included in Initial Spare Parts	Sketch	Cross Reference Drawing	expected frequency of replacement	Remarks			
		Level 0 (Total Plant)		Level 1 (System Code)			Level 2 (Equipment Code)			Level 3 (Component Code)						nr., pcs, set, etc	nr., pcs, set, etc	(See Item 2.7 of Instrm SH)	(See Item 2.8 of Instrm SH)								
		G	F ₁	F ₁ F ₁ F ₁	F ₁	A ₁ A ₁	A ₁	A ₁	B ₁ B ₁	B ₁																	
354	424	5	0	HJ	02	AC	001				KC	01-87	Final reheater	Final reheater tube Ø57.3x3.2x1000mm Code case 2329-2	NIPPON STEEL & SUMITOMO METAL CORPORATION	N/A	5	PCS	4	PCS				N/A	TJ856-L2-OFF-JS-H4-G-80D-0001 TJ856-L2-OFF-JS-H4-G-80D-0001	N/A	
355	425	5	0	HJ	02	AC	001				KC	01-87	Final reheater	Final reheater tube Ø57.3x3.2x1000mm Code case 2329-2	NIPPON STEEL & SUMITOMO METAL CORPORATION	N/A	5	PCS	4	PCS				N/A	TJ856-L2-OFF-JS-H4-G-80D-0001 TJ856-L2-OFF-JS-H4-G-80D-0001	N/A	
356	426	5	0	HAH	01	AC	001						Attemperator	Superheater 1st stage attemperator spray nozzle Inconel equivalent	MHPS	N/A	1	PCS	1	PCS				N/A	TJ856-L2-OFF-JS-H4-G-80D-0001 TJ856-L2-OFF-JS-H4-G-80D-0001	N/A	
357	427	5	0	HAH	02	AC	101						Attemperator	Superheater 2nd stage attemperator spray nozzle Inconel equivalent	MHPS	N/A	1	PCS	1	PCS				N/A	TJ856-L2-OFF-JS-H4-G-80D-0001 TJ856-L2-OFF-JS-H4-G-80D-0001	N/A	
358	428	5	0	LBC	03	AC	001						Attemperator	Reheater attemperator spray nozzle Inconel equivalent	MHPS	N/A	1	PCS	0	PCS				N/A	TJ856-L2-OFF-JS-H4-G-80D-0001 TJ856-L2-OFF-JS-H4-G-80D-0001	N/A	
1165	5	6											Waterwall	Membrane Bar (SA-387MGr.12 / 6.4)(6.0)x31.8Wx90~1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1167	5	6											Waterwall	Membrane Bar (SA-387MGr.22 / 9.0)(31.8Wx120"-1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1168	5	6											Waterwall	Membrane Bar (SA-387MGr.22 / 12.0)(50.9Wx120"-1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1169	5	6											Waterwall	Membrane Bar (SA-387MGr.22 / 9.0)(57.4Wx120"-1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1170	5	6											Waterwall	Membrane Bar (SA-387MGr.12 / 6.4)(6.0)x57.4Wx90~1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1171	5	6											Waterwall	Membrane Bar (SA-387MGr.12 / 6.4)(6.0)x17.0Wx90~1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1172	5	6											Waterwall	Membrane Bar (SA-387MGr.12 / 6.4)(6.0)x14.9Wx90~1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	
1173	5	6											Waterwall	Membrane Bar (SA-387MGr.12 / 6.4)(6.0)x76.3Wx90~1500)	MHPS	N/A	20	pcs						N/A		(1) This estimate has membrane bars for standard pitch of each panel. Excludes membrane bars in special pitch such as water wall ends. (2) As the specifications for repairing membrane bars vary from place to place, please contact MHPS in advance.	

Uncontrolled when printed or downloaded. Verify that this is the correct version before use.
 Reproduction of part or all the contents of the document is prohibited without written permission from PT. Bhumi Jepara Service