	Equipment Tag Number (KKS)								el 3				Manufacturer's Part	Qty per two Units		Sketch	Cross Reference Drawing	Frequency of replacement	Remarks	
Item No.	(Total Plant)		System Co		(Equi	pment	nt Code)	(Compon	nent Code)	Spec No.	Equipment Name	Description of Spare Items	Identification	1 (22 222				_		Qty difference
	G	F ₀	F ₁ F ₂ F ₃	F _N	A ₁ A ₂	A _N	A ₃	B ₁ B ₂	B _N					Qty	(nr., pcs, set, etc)	(See Item 2.11 of Instrn Sht)	(See Item 2.12 of Instrn Sht)	95555	Item No. of CDA	from Qty of CDA
138																	D. P. W. F. C.	25000h		
										67,9281		Bearing		1	pcs					5→1
												_			, ·					
139	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD							3311&NJ2311		16000h		
139																	220004//	1600001		
										67,9281		Mechanical seal		1	pcs					5→1
															'		The state of the s			
140	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD							M7N/65				
140																		5 years		
										67.9281		Casing insert (screw pumps)		1	pcs					3→1
												,					in the second			
	TBD TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	67.9281						2HMG2500C-01(ZG230)				
141	IBD	IBD	IBD	IBD	IBD	IBD	IBD	IBD	IBD	67.9281		O-ring and gasket		1	pcs	2HMG280-22/103	N/A	Every disassemble the pump 25000h	New Item New Item	
					1			1						1						
					1			1		67.9281		Bearing		1	pcs					
	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD							3305&NJ2305	refer to pdf drawing attachment 1			
143																	, , , , , , , , , , , , , , , , , , , ,	16000h	New Item	
					1			1		67,9281		Mechanical seal		1	pcs					
					1					51.5201		Wooding (Call Strain		1 "	~~					
111	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD					1		M7N/30	refer to pdf drawing attachment 2		N	
144																		5 years	New Item	
										67.9281		Casing insert (screw pumps)		1	pcs					
														1		0.11400000	and the second s			
145 146	TBD TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD TBD	TBD TBD	67.9281		O-ring and gasket		1	pcs	2HMG280C-01(ZG230) 2HMG1400-22/103	refer to pdf drawing attachment 3 N/A	Every disassemble the pump 25000h	New Item	
146																		25000h	New Item	
										67.9281		Bearing		1	pcs					
					1			1						1	l .					
147	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD					+		3309&NJ2309		16000h	New Item	
										67.9281		Mechanical seal		1	pcs					
Ш	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD							M7N/50				
148										7							XX	5 years	New Item	7
										67.9281		Casing insert (screw pumps)		1	pcs					
	TPP		TBD	TDD			100	TOO	TES					1		2LIMO11000 01/70005				
149	TBD	IBD	IBD	IBD	IBD	IBD	IBD	TBD	TBD					 		2HMG1400C-01(ZG230) U-RING:110.720 MM-3.530 MM-	10. 1	Every disassemble the pump	New Item	
										67.9281		O-ring and gasket		2	pcs	245 O-RING:126.590 MM-3.530 MM-				
	TRD	TRD	TRD	TRD	TRO	TRD	TRD	TRD	TRD					-		250	NA			
150	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	67.9281		Bearing		2	pcs	Gasket:1500×600×0.381 7311/BE CB M P6/P5,6213/C3	NA NA	25000h 25000h	New Item New Item	
151																	100 mm	25000h	New Item	
										67.9281		Mechanical seal		2	pcs					
																	Section 1982			
152	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD					_		NA NA				
153											Start-up boiler							Force (Expected)	B3-3-SP-1	
153																//		Force (Expected)	B3-3-5P-1	
																FIA				
										67,6150		I gnitor		2	pcs	link link				
	TBD	TBD	TBD	TDD	TEC	TDD	TBD	TBD	TBD							4 4 4 4				
154	IBD	IBD	IBD	IBD	IBD	IBD	IBD	IRD	IBD					 				failure,(>2years)	B3-3-SP-2	
					1									1						
					1			1						1						
										67.6150		Flame detector		1	pcs					
					1									1						
	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	I						burner-No3	0			
																		•		